

STREET-BY-STREET EPC DATA FOR STEYNING, BRAMBER & UPPER BEEDING

Town	Road	No. of homes with an EPC certificate	CURRENT EPC RATING						% C or better	POTENTIAL EPC RATING							% C or better
			A	B	C	D	E	F		G	A	B	C	D	E	F	
Bramber	Annington Road	6				1	3	2	0%			2	2	2			33%
Bramber	Botolphs Road	8			1	2	4	1	13%		1	2	3	1		1	75%
Bramber	Castle Close	1		1					100%		1						100%
Bramber	Castle Field	2			2				0%				2				0%
Bramber	Castle Lane	13			2	7	4		15%		6	4	2	1			77%
Bramber	Clays Hill	21		2	10	3	5	1	57%		1	4	11	5			76%
Bramber	Coombe Drove	14		2	1	6	5		21%		1	3	6	4			71%
Bramber	De Braose Way	11			5	6			45%			7	3	1			91%
Bramber	Little Drove	2			1		1		50%				1		1		50%
Bramber	Maudlin Lane	11			3	2	6	1	18%		1	3	7				100%
Bramber	Maudlyn Close	3			3				100%		1	1	1				100%
Bramber	Maudlyn Park	1			1				100%				1				100%
Bramber	Maudlyn Park Way	10			3	6	1		30%			8	2				100%
Bramber	Sopers Lane	6			3	1	2		50%			1	4		1		83%
Bramber	The Ridings	11			2	6	2	1	18%			1	8	1	1		82%
Bramber	The Street	33		6	6	12	6	3	36%		4	13	11	2	2	1	85%
Steyning	Abbey Road	12			2	9	1		17%			7	4	1			92%
Steyning	Andrew Close	5				2	2	1	0%			1	3		1		80%
Steyning	Bank Passage	5			1		4		20%		2	2	1				100%
Steyning	Bostal Road	9			3	2	1	3	33%			3	1	4	1		44%
Steyning	Bowmans Close	10			4	5	1		40%			8		2			80%
Steyning	Bramber Road	15			10	4	1		67%			5	10				100%
Steyning	Breach Close	27			1	23	3		4%		1	19	7				100%
Steyning	Canons Way	12			4	6	2		33%			4	8				100%
Steyning	Castle Lane	12			4	5	3		33%			6	4	1	1		83%
Steyning	Castle Way	8			2	4	2		25%			3	5				100%
Steyning	Chandlers Way	11			2	9			18%			3	6	2			82%
Steyning	Charlton Street	36		3	12	16	5		42%		4	21	9	2			94%
Steyning	Church Mead	8			1	7			13%			2	5	1			88%
Steyning	Church Street	13				2	8	2	0%			1	4	2	5	1	38%
Steyning	Clivedale Gardens	1				1			0%				1				100%
Steyning	College Hill	30		5	19	2	2	2	80%			14	14	1	1		93%
Steyning	Coombe Road	30		1	5	18	6		20%			15	12	3			90%
Steyning	Coxham Lane	16			5	6	5		31%			8	7	1			94%
Steyning	Cripps Lane	2				1	1		0%			1	1				100%
Steyning	Dingeman Court	28			15	12		1	54%		2	7	16	3			89%
Steyning	Dog Lane	3				2	1		0%				1	2			33%
Steyning	Dukes Lane	1				1			0%				1				100%
Steyning	Dukes Yard	6			2	4			33%			1	5				100%
Steyning	Elm Grove Lane	8			1	3	4		13%			1	3	3	1		50%
Steyning	Elm Terrace	5			1	1	3		20%			5					100%
Steyning	Fairs Field	20		19	1				100%			19	1				100%
Steyning	Farnfold Road	26			16	7	3		62%		1	15	7	1	2		88%
Steyning	Godstalls Lane	6			1	4	1		17%				4	2			67%
Steyning	Goring Road	75		11	36	16	11	1	63%			24	47	3	1		95%
Steyning	Greenacres	12			2	9	1		17%			7	4	1			92%
Steyning	Henderson Walk	12			5	7			42%			7	5				100%
Steyning	High Street	59		2	11	18	21	5	22%			16	16	15	7	4	54%
Steyning	Highland Croft	6			3	2	1		50%			2	2	2			67%
Steyning	Hills Road	25		2	10	12	1		48%			15	10				100%
Steyning	Hillside Terrace	7				5	1	1	0%			1	3	2	1		57%
Steyning	Holland Road	5			2	2	1		40%			1	3	1			80%
Steyning	Horsham Road	81		2	41	18	13	6	53%		4	19	46	6	5	1	85%
Steyning	Ingram Close	4				2	2		0%			4					100%
Steyning	Ingram Road	19			4	11	4		21%			5	11	3			84%
Steyning	Jarvis Lane	40		1	4	19	14	1	13%			12	21	6	1		83%
Steyning	King Alfred Close	14		1	5	5	3		43%			11	2	1			93%
Steyning	Kings Barn Lane	39			9	19	9	2	23%		2	14	17	5	1		85%
Steyning	Kings Barn Villas	9			2	5	2		22%			1	7		1		89%
Steyning	Kings Stone Avenue	47			5	25	14	2	11%		1	10	25	10	1		77%
Steyning	Kingsmead Close	4				2	2		0%			1	1	2			50%
Steyning	Laines Road	23			6	12	4	1	26%			13	9	1			96%
Steyning	Market Field	14			1	6	5	1	7%			1	8	2	2	1	64%
Steyning	Middle Mead	11			3	8			27%		1	7	3				100%
Steyning	Mill Road	18		1	5	9	2	1	33%		1	7	8	2			89%
Steyning	Mimmack Close	9			3	6			33%		1	4	4				100%
Steyning	Mouse Lane	13			2	4	5	2	15%			5	4	3	1		69%
Steyning	Newham Close	19			5	13	1		26%		2	10	7				100%
Steyning	Newham Lane	34		1	13	16	3	1	41%		1	21	10	2			94%
Steyning	Normans Way	7			5	2			71%			3	3	1			86%
Steyning	Penfold Way	22			4	11	5	1	18%			10	5	7			68%
Steyning	Penlands Close	7		4	2	1			86%			6	1				100%
Steyning	Penlands Rise	22			3	13	6		14%			11	8	3			86%
Steyning	Penlands Vale	48			16	28	4		33%		1	26	18	3			94%
Steyning	Penlands Way	13			2	7	4		15%			5	8				100%
Steyning	Perrots Lane	2			1	1			50%			2					100%
Steyning	Portway	12			1	8	3		8%			9	1	1	1		83%
Steyning	Roman Road	28		2	2	18	5	1	14%			12	11	5			82%
Steyning	Rosemary Avenue	13			3	7	2	1	23%			8	4	1			92%
Steyning	Rosemary Close	6				5	1		0%			3	3				100%
Steyning	Saxon Road	15			3	7	4	1	20%			8	4	3			80%
Steyning	Sheep Pen Lane	4				2	2		0%			1	1	2			50%
Steyning	Shooting Field	79		7	30	31	9	2	47%		8	47	20	3	1		95%
Steyning	Sir Georges Place	16			3	9	4		19%		1	6	6	3			81%
Steyning	South Ash	24			14	9	1		58%			14	10				100%
Steyning	Southdown Terrace	5				2	2	1	0%			2	2		1		80%
Steyning	St Cuthmans Road	30			19	6	4	1	63%			2	24	4			87%
Steyning	Station Road	12			3	2	4	2	25%			3	5	2	1	1	67%
Steyning	Stonecroft	8		1	3	4			50%		1	6	1				100%
Steyning	Tanyard Lane	40		1	24	12	3		63%			18	17	4	1		88%
Steyning	The Crescent	11			4	4	3		36%			5	5	1			91%
Steyning	The Furlongs	5				4	1		0%			1	2	2			60%
Steyning	Thornscroft	11			6	5			55%		1	6	4				100%
Steyning	Toomey Road	39		2	25	11	1		69%			7	29	3			92%
Steyning	Vicarage Lane	1				1			0%					1			0%
Steyning	White Horse Square	8			1	4	2	1	13%			3	4			1	88%
Steyning	Willow Close	4				3	1		0%			1	1	2			50%
Steyning	Wyckham Lane	5			1	4			20%		1		2	2			60%
Steyning	Wykeham Close	6		1			3	2	17%			1	1	2	2		33%
Upper Beeding	Castletown	4				1	3		0%			2	1		1		75%
Upper Beeding	Church Close	7			2	5			29%		1	4	2				100%
Upper Beeding	Church Farm Walk	5			1	4			20%			5					100%

